

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, September 12, 2018	Project Contact:	Brian Clauto
Spread: Franklin County	Spread H	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)									
	Clearing Rough Grading Trench Excavation				\boxtimes	Pipe Assembly, Testing & Installation			
	ckfilling and Grade Restoration Final Grading & Stabilization				Other: Storm preparation				
		Yes	No	N/A					
1	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								
2	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?	\boxtimes							
3	Areas of offsite sediment deposition were observed?		\boxtimes						
	·								
Comments: Area 1 - MP 246.54 station#13013+20 - 13017+55 tie in crews working on this section of pipe and lowering / backfilling in this area, dewatering structure in place. Area 2- In the area of MP 252.21 St#13317+00 – 13320+00 blanket matting has been installed									
Deadline: N/A									
The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.									
Inspector Signature: Date:9-17-18									



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Wednesday, September 12, 2018

Fig. 1 MP 246.47 St#13014+00 dewatering structure in place



Fig. 3 In the area of MP246.43 St# 13012+00 area has been matted.



Fig. 2 MP 246.46 St#13013+35 portions of pipe have been lowered.



Fig. 4
MP 252.21 St#13317+00 – 13320+00 blanket matting has been installed.

